

dividing walls in the new toilet facilities evidently did not have any foundations, apparently having been built straight onto the existing concrete slabs. It was noted that there were some 9 inch thick brick walls in the Male Toilets, it being considered that any hooliganism or vandalism would be more likely to occur there than in the Female Toilets.

The Club pointed out that the new toilet facilities would not be completely finished by the first match of the season (on 17th August) but that temporary facilities would be available and that no building material would be left on site.

The position of the new refreshment area under the most westerly staircase up to the North-West corner terrace was noted. This again had been built straight onto the existing concrete slabs.

On the Terrace itself, it was noted that there was an existing gate in the new 2 m. wide gap formed by the new radial fence for use by the Police. This gate would still be available for the use of spectators in an emergency as the gates at the top of the Terrace under the control of the Police would enable spectators to be directed down the 2 m. wide gap. However, it was agreed that steps or a longer gate would be required. It was also agreed that a new gate would be required from the new South Central Terrace Pen.

As regards the upper seated stand area, Messrs. Eastwood and Partners had sent by letter dated 2nd August plans of the new fences and barriers in both the Stand and at the Access level.

IT WAS AGREED:-

- (a) that the condition of the internal walls in the new male and female toilet facilities at the rear of the Stand should be monitored;
- (b) that the existing gate in the pitch perimeter fence should either be extended or have steps to provide easier access from the new 2 m. wide gap formed by the new radial fence;
- (c) that a new gate in the pitch perimeter fence should be provided from the new South Central Terrace Pen;
- (d) that the advertising hoardings at the front of the upper seated stand area should be securely fixed to the concrete wall;
- (e) that the spalling of the concrete of the wall at the front of the upper seated stand area should receive attention as a matter of maintenance;
- (f) that the corrosion of the steel columns at the rear of the Stand should receive attention on a maintenance basis.

B. South Stand

Messrs. Eastwood & Partners reported that the condition of the upper concrete outer portion of the exterior wall of the Stand had been investigated and was considered to be satisfactory.

It was noted that the metal sheeting of the wooden upper portion of the Stand had been largely completed, and the spraying of the non-slip surface was to commence very shortly (and certainly be completed by the start of the season).