

# EASTWOOD & PARTNERS

(Consulting Engineers)

Directors

**W. Eastwood**

B.Eng. B.Eng. Ph.D. C.Eng.  
C.Eng. F.I.C.E. F.P.S. Struct. E.  
F. Mach. E. F.G.S. M. C. Eng. E.

**A.A. Wood**

B.Eng. Ph.D. C.Eng. F.I.C.E.  
F. Struct. E. M. W. E. M. M. Course E.

**R.C.A. Eastwood**

B.Sc. C.Eng. M.I.C.E. F. I. C. E.

**G. Spir**

C.Eng. F.I.C.E. M. I. Mech. E.

**C.S. Greaves**

B.Eng. C.Eng. M.I.C.E. M. I. Mech. E.

**S. Preston**

B.Eng. C.Eng. M.I.C.E. M. I. Mech. E.


**G.M. Seaman**

B.Sc. C.Eng. M.I.C.E. F. I. C. E.

**D.S. Stephens**


C.Eng. F.I.C.E. F. I. C. E. F. I. C. E.

St. Andrews House  
23 Kingfield Road  
Sheffield S11 9AS  
Tel.: (0742) 554554  
Fax: (0742) 554330



and at

Premier House  
12/13 Hatton Garden  
London EC1N 8AN  
Tel.: (01) 242 7436  
Fax: (01) 404 5424



WE/KB/

Administration and Legal Department,  
Sheffield City Council,  
Town Hall,  
Sheffield 1.

4 January 1990

*F.W. C.P.*  
*D.S.*  
*J.S.*

For the attention of Mr. W.J. Derricott

Dear Mr. Derricott,

Sheffield Wednesday Football Ground

Capacity of North West Corner

Please excuse the delay in giving a detailed response to your letter of 6 December 1989. I needed to have some checks made on the measurements of the terrace. Arrangements were made for these measurements to be made on two occasions. Each time there was heavy rain all day. The work was completed just before Christmas.

By way of background, you will no doubt be aware that we did not carry out a survey of the Leppings Lane end of the ground when the original Safety Certificate was applied for in 1978-79. The Club provided drawings prepared by their previous consultants of the North stand, the West stand the North West corner from which we made measurements. There were no drawings available of the older parts of the ground (the Kop and the South stand) and we were commissioned by the Club to make the necessary measurements on site, for which we quoted a specific fee. This is all well documented in our correspondence with the Club at the time and in our report to them of January 1979.

We have now measured the upper part of the North West corner, and there is a considerable discrepancy between the actual measure-

Associates:

**J. A. Strange**  
C.Eng., F.I. Struct. E.

**A. J. Clough**  
B.A., C.Eng., M.C., B.Sc.,  
M.I. Mech. E.

**R. Tandy**  
C.Eng. F. Struct. E.

**J. M. Wood**  
B.Sc., C.Eng., M.I.C.E.,  
M.I. Struct. E.

**C. M. Pollard**  
B.Eng., C.Eng., M.I.C.E.,  
M.I. Struct. E.

**R. K. Godden**  
F.S.C.A. Accountant  
& Administration  
Manager

An Unlimited Company. Registered in England - No. 1833144

451

SYP000038710187