

B. West Terrace

IT WAS AGREED -

1. That the Club's proposals for the installation of additional barriers and the reduction in capacity to 7,200 spectators without the need for additional gangways should be implemented.
2. That the question of the cross-fall on the steps on the north-west corner exit, the height of some of the existing crush barriers, as well as their corrosion and sharp edges in places, be the subject of detailed discussion between Dr. Eastwood and the Building Surveyor. ✓

C. North West Corner Terrace

IT WAS AGREED -

1. That the Clubs proposals to bring the crush barriers up to standard and supplemented by new barriers with a consequent capacity of 2,900 spectators should be implemented. ✓
2. That the improvement or replacement of the existing corrugated sheeting be the subject of detailed discussion between Dr. Eastwood and the Building Surveyor. *not done*

3. North Stand

IT WAS AGREED -

1. That, in view of the obvious difference of opinion between the Club and the Working Party as to the appropriate steps (if any) to be taken over the width of the existing gangways, both sides be requested to consider all the points made, and to re-consider the matter at the next meeting. ?
2. That the question of fire protection works to the Store Room and to the Team Room be the subject of detailed discussions between Dr. Eastwood and the Fire Service. ?
3. That the replacement (from a fire hazard point of view) of the existing Police and First-Aid Temporary Structures under the Stand be accepted in principle, and that the facilities required in the new permanent structures be considered later in the Agenda. ?
4. That the existing Wire Mesh barriers under the Stand be the subject of discussions between Dr. Eastwood and the Fire Service. P
5. That the question of the provision of handrails be the subject of discussions between Dr. Eastwood and the Building Surveyor. ?

3.