

Document No. 83 CONT'D

ments and those scaled from the drawing based upon that provided by the Club. Instead of the 2900 which had notionally been considered to be the capacity of the upper North West corner, the total area available would only take 2242 on the basis of 54 spectators to 10m<sup>2</sup>.

The discrepancy between the drawing and the actual measurement is not in any way apparent from a visual inspection of the terrace. At the time when we were reporting in 1979, we were made aware that in September 1970, following a report by the Club's previous consultants the police had agreed a capacity for the elevated North West corner of 3,000 spectators. That figure or a higher one had been used in all the major games from the World Cup in 1966. There was thus no reason for us to be alerted in 1978/79. We enclose a copy of the 1970 report and the Chief Constable's letter to the Club dated 30 September 1970.

Obviously we have been concerned about the possibility that the calculations for the terrace in front of the West stand might also have been based on a misleading plan. Our check measurements have shown that the actual area is such that it could accommodate the 'notional' number of spectators with a slightly lower density than 54 per 10m<sup>2</sup>.

Yours sincerely,

*W. Eastwood*